

Mounting location for accurate measurements:

Choose a location that is not subject to direct weather elements. An ideal location is out of direct sun, on the North side of a building or in a shady spot.

Mounting instructions:

Assemble the stainless steel rod and insert it into the ground in the desired location. Next, gently slide the thermometer dial onto the rod for a snug fit.