

Mounting location for accurate measurements:

Choose a location that is not subject to direct weather elements. An ideal location is out of direct sun, on the North side of a building or in a shady spot.

Mounting on nail or screw:

Hang the thermometer from a long nail or screw (not included) with the built in key hole

Secret key hider compartment:

Secret key hider compartment on back of thermometer stores spare keys so you'll never be locked out again.