

## **Mounting location for accurate measurements:**

Choose a location that is not subject to direct weather elements. An ideal location is out of direct sun, on the North side of a building or in a shady spot.

## **Mounting on nail or screw:**

Hang the thermometer from a long nail or screw (not included) with the built in key hole.

## **Secret key hider compartment:**

Secret key hider compartment on back of thermometer stores spare keys so you'll never be locked out again.