WARRANTY & SUPPORT

Equity provides a 2-year limited warranty on this product from the date of consumer purchase against defects for material and workmanship. During this period such defects will be repaired, or the product will be replaced at Equity's option, without charge. This warranty does not cover damage caused by misuse or negligence.

ALL IMPLIED WARRANTIES, INCLUDING BUT NOT LIMITED TO IMPLIED WARRANTIES OR FITNESS AND MERCHANTABILITY, ARE LIMITED IN DURATION TO A PERIOD ENDING TWO YEARS FROM DATE OF PURCHASE.

Some states do not allow limitations on how long an implied warranty lasts so the above limitation may not apply to you. This warranty gives you specific legal rights and you may also have other rights which vary from State to State.

If your product is not working properly, please send: Your product

A letter explaining the problem and \$5.00 for postage and handling to: Equity by La Crosse

Warranty Department

2830 26th St S. La Crosse, WI 54601

www.lacrossetechnology.com/support



WARNING: This product can expose you to chemicals including styrene, which is known to the State of California to cause cancer. For more information go to: www.P65Warnings.ca.gov

Made in China - Printed in China Page | 4



7-INCH COOL MIST WALL/TABLE CLOCK



Model: 20860 DC: 091018


Page | 1

POWER UP

- 1. Insert 1 fresh AA battery into your clock according to the polarity markings.
- 2. Rotate the Time Set Wheel to set your time.

3. Enjoy!

Note: The quartz movement will keep the clock running accurately. If the clock does not operate, or steadily loses time, replace the battery.



POSITION

- Mount your clock on a wall using the hanging hole on the back of the clock.
- Place you clock on desk or table.

SPECIFICATIONS

Battery Requirements: 1 AA (IEC LR6) required in movement (Alkaline recommended)

Battery life: 12 months

CARE & MAINTENANCE

- Always purchase the correct size and grade of battery most suitable for intended use.
- Clean the battery contacts and also those of your clock prior to battery installation.
- Ensure the battery is installed with correct polarity (+ and -).
- Remove battery from equipment when it is not used for an extended period of time.
- Promptly remove an expired battery.